

## Yamaha DTX-MULTI 12 Firmware V1.02 Release Notes

---

### Main Revisions and Enhancements

#### 【V1.01 to V1.02】

- Fixed a bug where, when two HH65 Hi-hat Controllers connected to the FOOT SW and HH CTRL jacks were simultaneously operated, a sound would be produced only for one of them.

#### 【V1.00 to V1.01】

- Added the following new Pad Type parameters for external pads to the DTX-MULTI 12.

New Pad Type	Model
KP125W/125	KP125W/125
XP120/100Sn	XP120SD/100SD
XP120/100Tm	XP120T/100T

- Fixed a problem in which the DTX-MULTI 12 may freeze along with the loss of currently recorded data, when the recording operation uses up the full memory for User patterns.
- Solved some minor errors.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

©2010–2012 Yamaha Corporation. All Rights Reserved.